





	0		R	
Ax8	Bx8	Cx2	Dx2	Ex4
6,4x40	M8x16	M8x20	6,4×70 ⊕⊃⇒>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	
Fx20	Gx8	Hx56	lx8	Jx1
				3,5x30
Kx1	Lx12	Mx4	Nx8	Ox40
	4×16	M6x20		
Px1	Rx48	Sx12	Tx4	Ux8














screw all bolts 100%





























10 **x2 x2** Lx2

