






ASSEMBLY INSTRUCTIONS


No	Name of Hardware	Fig	Q.ty
1	Botl M6x50		8
2	Washer 6x20x2		8
3	Allen Key		2












Step 1:




Step 2:




ASSEMBLY INSTRUCTIONS

No	Name of Hardware	Fig	Q.ty			
1	Screws M6x60		4	 1x	 1x	 1x
2	Screws M6x35		4			
3	Botl M6x35		4	 1x	 1x	 2x
4	Allen Key		2			


Step 1:




Step 2:












Step 3:




Step 4:




ASSEMBLY INSTRUCTIONS

No	Name of Hardware	Fig	Q.ty			
1	Screws M6x60		4	 1x	 1x	 1x
2	Screws M6x35		4			
3	Botl M6x35		4	 1x	 1x	 3x
4	Allen Key		2			


Step 1:




Step 2:











Step 3:




Step 4:




ASSEMBLY INSTRUCTIONS

No	Name of Hardware	Fig	Q.ty						
1	Screws M6x60		4		1x		1x		1x
2	Screws M6x35		3						
3	Botl M6x35		4		1x		1x		1x
4	Botl M6x40		4						
5	Allen Key		2						


Step 1:




Step 2:



ASSEMBLY INSTRUCTIONS



Step 3:



Step 4:

