





TIMMINS














1/12

2545/TIMMINS/140325/




2/12



2545/TIMMINS/140325/

 x 1	 x 1	 x 1
 x 1	 x 1	 x 1
 x 1	 x 1	 x 4
 x 1	 x 1	 x 4
 x 1		

3/12

2545/TIMMINS/140325/

A  x 30	B  x 18	C  x 4	D  x 17
E  x 12	F  x 1	G  x 4	H  x 16
I  x 4	J  x 2	K  x 28	L  x 4
M  x 4	N  x 2	O  x 1	P  x 1







4/12

2543/TIMMINS/1 40325/

5/12

2543/TIMMINS/1 40325/







6/12

2543/TIMMINS/1 40325/

7/12

2543/TIMMINS/1 40325/







8/12

2545/TIMMINS/140325/

9/12

2545/TIMMINS/140325/



10/12

2545/TIMMINS/140325/

11/12

2545/TIMMINS/140325/

15

I
M4
x
25
x 4

