



Assemble Instruction




HardwareList

A		20	F		2
B		20	G		10
C		20	H		8
D		4	I		32
E		4			1

Parts List




Step 1



A		12
B		12
C		12


Step 2



x2


C		4	F		2
E		4	H		8
D		4			

Step 3




A		8
B		8
C		4

Step 4



G		8
---	--	---



G		2
I		32