




ASSEMBLY INSTRUCTION

(1)×1 	A×2 M6*16 
(2)×1 	B×10 M6*25 
(3)×1 	C×4 M6*43 
(4)×1 	D×4 
(5)×1 	E×12 
(6)×1 	F×1 
(7)×4 	G×2 


1



2




3




Remark: Rotate mechanical 90° by hand to expose the assembly locking hole position, and then insert tool part "G" into the hole to locking mechanical for screws assembly.

4



5



Remark: Pull out Part "G", and then rotate mechanical in the opposite direction to reveal the other two assembly holes.

6

