



Assemble Instruction




HardwareList

A		20	F		2
B		20	G		8
C		20	H		32
D		4			1
E		4			

Parts List




Step 1



A		12
B		12
C		12


Step 2



x2


C		4	F		2
E		4	G		8
D		4			

Step 3



A		8
B		8
C		4

Step 4



H		32
---	--	----