


ASSEMBLY INSTRUCTIONS




40'





2

1




2

A	x 48	B	x 48	C	x 48
					
$\phi 6 \times 35\text{mm}$		$\phi 15 \times 12\text{mm}$		$\phi 8 \times 30\text{mm}$	
D	x 20	E	x 4	F	x 6
					
$\phi 7 \times 40\text{mm}$		M3.5 x 12mm		M6 x 40mm	
G	x 8	H	x 4	I	x 4
					
M6 x 30mm		M6 x 15mm		M6 x 12mm	
J	x 4	K	x 4	L	x 2
					
				M4	
M	x 16	N	x 4	O	x 4
					
M4 x 35mm				M4 x 18mm	
P	x 2				
					
M4 x 35		M3.5 x 12			


3

1



L	x 1	C	x 4	D	x 4
					
M4		φ 8 x 30mm		φ 7 x 40mm	


2



A	x 4
	
φ 6 x 35mm	


4

3



B	x 4	C	x 4
			
φ 15 x 12mm		φ 8 x 30mm	


4



E	x 2
	
M3.5 x 12mm	


5

5



C	x 4	D	x 4
			
φ 8 x 30mm		φ 7 x 40mm	


6



A	x 4
	
φ 6 x 35mm	


6

7



B	x 4	C	x 2
			
φ 15 x 12mm		φ 8 x 30mm	


8



E	x 2
	
M3.5 x 12mm	


7

9



C	x 4	D	x 4
			
$\phi 8 \times 30\text{mm}$		$\phi 7 \times 40\text{mm}$	


10



A	x 4
	
$\phi 6 \times 35\text{mm}$	


8

11



B	x 4	C	x 2
			
$\phi 15 \times 12\text{mm}$		$\phi 8 \times 30\text{mm}$	


12



A	x 12
	
$\phi 6 \times 35\text{mm}$	


9

13



B	x 12	C	x 12
			
$\phi 15 \times 12\text{mm}$		$\phi 8 \times 30\text{mm}$	


14



A	x 8
	
$\phi 6 \times 35\text{mm}$	


10

15




B	x 8	C	x 8
			
$\phi 15 \times 12\text{mm}$		$\phi 8 \times 30\text{mm}$	

16




11

17




18




12

19




20



13


21



14


22

x 4



23


x 4



15

24


x 4



A	x 16
$\phi 6 \times 35\text{mm}$	

25


x 4



N	x 4	0	x 4	B	x 16
		$M4 \times 18\text{mm}$		$\phi 15 \times 12\text{mm}$	



16

26



17

27



P	x 2
$M3.5 \times 12$	

18