



Assemble Instruction




Parts List



HardwareList


A	M6*90	18	F		2
B	M10*15	18	G	M7*50	10
C	M8*30	20	H	M4*15	8
D	M6*40	4	I	M4*30	32
E	M8*18	4			1

Step 1




A	M6*90	10
B	M10*15	10
C	M8*30	12

Step 2




C	M8*30	4	F		2
E	M8*18	4	H	M4*15	8
D	M6*40	4			

Step 4




G	M7*50	8
---	-------	---

Step 3



A	M6*90	8
B	M10*15	8
C	M8*30	4

Step 5



G	M7*50	2
I	M4*30	32