

















1



2



E.10  6.5x30	x8	A.13  Ø4x40	x4	B.12  Ø12x30	x12
B.15  Ø7x50	x8	A.27  Ø6,3x13	x16	B.50  №4	
A.21  Ø4.2x19	x24	F.28 	x4	A.8  Ø4x20	x14
F.26 	x2	F.27 	x2		



№		Sizes	Coll
1	x1	1250(1450;1650;1850;2050)x160x25	
2	x1	1250(1450;1650;1850;2050)x160x25	
3	x2	2050x160x50	
4	x2	510x65x20	
5	x2	232x65x65	
6	x2	232x65x65	
7	x1	1252(1452;1652;1852;2052)x320x20	
8	x1	1985x80x20	
9	x2	205x70x20	

1




A.27



x8

F.28


x4




Ø6,3x13



PZ 2




4x




5

2




A.27


x8




Ø6,3x13



PZ 2



4x




6




3

A.21


x24




Ø4.2x19



PZ2




7



4


E.10

x8




6.5x30

B.50



Nº4




8




5

B.12


x12



Ø12x30




9



6


B.15

x4





Ø7x50


B.50



№4




10




7

F.27




x2

A.8






x8

Ø4x20




PZ 2




8

A.13





x4

Ø4x40



PZ 2






x6




Ø4x20


x4



Ø7x50




F.26

 x^2 

B.50

 $2x$

x1



No.

180






9

9

 $2x$

10

 $2x$  $2x$

14