



Assemble Instruction




Parts List




HardwareList

|   |        |    |   |       |    |
|---|--------|----|---|-------|----|
| A | M6*90  | 18 | F |       | 2  |
| B | M10*15 | 18 | G | M4*15 | 8  |
| C | M8*30  | 20 | H | M4*30 | 32 |
| D | M6*40  | 4  |   |       | 1  |
| E | M8*18  | 4  |   |       |    |




|   |        |    |
|---|--------|----|
| A | M6*70  | 10 |
| B | M10*15 | 10 |
| C | M8*30  | 12 |




|   |       |   |   |       |   |
|---|-------|---|---|-------|---|
| C | M8*30 | 4 | F |       | 2 |
| E | M8*18 | 4 | G | M4*15 | 8 |
| D | M6*30 | 4 |   |       |   |

Step 4



|   |       |    |
|---|-------|----|
| H | M4*30 | 32 |
|---|-------|----|

Step 3



|   |        |   |
|---|--------|---|
| A | M6*70  | 8 |
| B | M10*15 | 8 |
| C | M8*30  | 4 |

