



1-10



2-10

1



M4x10

x20

2^A



2A

x2

2^B



2B

x2

3^A



3A

x2

3^B



3B

x2

3^C



M4x22
3C

x2

4



x4

5^A



M4x35mm
5A

x2

5^B



M5
5B

x2

5^C



M8
5C

x2

6



x12

7^A



x4







7^B





x4

3-10

1











2




① x4
M4x10


4-10



11




13



10-10

12



9-10