



Assemble Instruction




HardwareList

|   |  |    |   |  |    |
|---|--|----|---|--|----|
| A |  | 20 | F |  | 2  |
| B |  | 20 | G |  | 10 |
| C |  | 20 | H |  | 8  |
| D |  | 4  | I |  | 32 |
| E |  | 4  |   |  | 1  |

Parts List




Step 1



|   |  |    |
|---|--|----|
| A |  | 12 |
| B |  | 12 |
| C |  | 12 |


Step 2



x2


|   |  |   |   |  |   |
|---|--|---|---|--|---|
| C |  | 4 | F |  | 2 |
| E |  | 4 | H |  | 8 |
| D |  | 4 |   |  |   |

Step 3




|   |  |   |
|---|--|---|
| A |  | 8 |
| B |  | 8 |
| C |  | 4 |

Step 4



|   |  |   |
|---|--|---|
| G |  | 8 |
|---|--|---|



|   |  |    |
|---|--|----|
| G |  | 2  |
| I |  | 32 |