



1-10



2-10

1



M4x10

x20

2^A



2A

x2

2^B



2B

x2

3^A



3A

x2

3^B



3B

x2

3^C



M4x22
3C

x2

4



x4

5^A



M4x35mm
5A

x2

5^B



M5
5B

x2

5^C



M8
5C

x2

6



x8

7^A



x4



7^B




x4

3-10

1











2



① x4
M4x10


4-10




11

③	Ø	→
3Ax2	3Bx2	M4x22 3Cx2

⑦	7A	7B	x4
---	----	----	----



13




10-10

12

Jx1	Kx1
-----	-----

②	2A	2B	x2
---	----	----	----



9-10