













 4x45	A 12	U 1	
 4x30	B 20	W 4	
 4x16	C 16	X 1	
	D 8	Y 1	
	E 16	Z 1	


 4x16	C 8
	E 16




* EN - Lack of glue or poor screw tightening will result in instability of the table

	D 8
	U 1




W 4	
--------	---



Detach the MDF plates by taking out two screws.

X






1

Y



1




4x45



A

12


X




1




X



X








W









X

W

Tighten the screws as much as possible.



Tighten the screws as much as possible.



- * EN - Lack of glue or poor screw tightening will result in instability of the table
 DE - Mangelnder Klebstoff oder schlechtes Anziehen der Schrauben führen zu Instabilität des Tisches
 PL - Brak użycia kleju lub zbyt słabe dokręcenie śrub spowoduje niestabilność stołu
 CZ - Nedostatek lepidla nebo špatné utažení šroubů bude mít za následek nestabilitu stolu
 SK - Nedostatok lepidla alebo zlé utiahnutie skrutiek bude mať za následok nestabilitu stola
 FR - Le manque de la colle ou un mauvais serrage des vis entraîne une instabilité de la table
 IT - L'assenza della colla o un insufficiente serraggio delle viti causerà l'instabilità del tavolo