





HENRIETTE




A x 4	B x 4	C x 1	D x 1	E x 1
F x 20	G x 4	H x 20	I x 1	J x 4
K x 4	L x 2	M x 2	N x 4	O x 4
P x 4	R x 4	S x 1	T x 4	

① x 1 (C1)	② x 1 (C1)	③ x 1 (C1)	④ x 1 (C1)
⑤ x 1 (C2)	⑥ x 1 (C2)	⑦ x 1 (C3)	⑧ x 1 (C4)



M8x50




l x 1

R x 4

3

1






B x 4



M8x20



M8x30




l x 1

H x 12


T x 4

2



screw all bolts 50%

3




$XX = YY \equiv 90^\circ$


screw all bolts 100%



3.5x30
F x 8


4







A x 4 F x 12 J x 4 K x 4

5






C x 1



D x 1




H x 8




I x 1

6




x2

H 4X



G x 4




M x 2




E x 1

7



x2

G 2X






09x8

O x 4

8






P x 4





E x 1

9





10

Option A



Option B






L x 2




M6x16
N x 4




S x 1

11



12



13

