












No	Name of Hardware	Fig	Q.ty	A	B	C	D	E
1	Bolt M8x50		6	 1x	 1x	 1x	 1x	 1x
2	Bolt M8x30		4					
3	Screw M6x60		8					
4	Screw M6x15		8	 1x	 4x	 2x	 1x	
5	Allen Key		2					

Step 1:




2x


Step 2:




Step 3:




Step 4:



Step 5:



Step 6:



Step 7: