










KUH.70588



KUH.40122



KUH.60176


KUH.60175

KUH.40120

KUH.10242


KUH.40120

KUH.10242




max.
5kg




 A 12	 K 2	 P8 4	 P7 15-20	 L2 3	 K36 1	 R2 2
 HG 2	 P5 6	 B 12	 O 1	 K16 2	 S 1	 E1 12
+8x30mm	+35/0mm	+4.0x30mm	+3.0x20mm	+3.0x25mm	+4.0x30mm	+3.5x13mm
6,4 x 50mm	L=128mm	L=128mm	L=128mm	L=128mm	L=128mm	L=128mm




ISM-KUH-01609




SMART



Colli
1/3




KUH.10246	1045x550x16mm	x1
KUH.10298	1045x550x16mm	x1




KUH.10299	815x550x16mm	x1
KUH.10300	815x550x16mm	x1
KUH.50014	668x486x16mm	x1
KUH.60264	683x500x2,5mm	x1
KUH.70931	496x128x16mm	x1
KUH.70695	677x496x16mm	x1
KUH.70696	545x496x16mm	x1

$\varnothing 6 \times 30 \text{mm}$	$6,4 \times 50 \text{mm}$	$\varnothing 6 \times 42 \text{mm}$	$\varnothing 16/12 \text{mm}$	$L=20 \text{mm}$
36	12	2	10	12
		$6,5 \times 48 \times 16$	$\varnothing 15 \times 5 \text{mm}$	$\varnothing 20/8 \text{mm}$
10	10	8	1	3
$\varnothing 35/0 \text{mm}$	$L=400 \text{mm}$	$\varnothing 5/16 \text{mm}$		$75 \times 30 \times 15 \text{mm}$
6	1	8	2	1
$\varnothing 6,3 \times 13 \text{mm}$	$\varnothing 5,0 \times 20 \text{mm}$		$\varnothing 12/10 \text{mm}$	$\varnothing 3,5 \times 13 \text{mm}$
3	3	1	2	20
$\varnothing 3,0 \times 20 \text{mm}$	$\varnothing 4,0 \times 30 \text{mm}$	$L=128 \text{mm}$		
12	8	4	2	

Colli
2/3




KUH.20083	601x568x16mm	x1
KUH.40008	567x485x16mm	x1
KUH.70582	908x596x16mm	x1
KUH.90010	567x100x16mm	x1
KUH.90116	567x130x16mm	x1



KUH.20113	1001x600x38mm	x1
KUH.30062	475x430x16mm	x1
KUH.40140	475x485x16mm	x1
KUH.40141	967x486x16mm	x1
KUH.60244	398x428x2,5mm	x1
KUH.90213	967x130x16mm	x1
WST.0211	400x80x12mm	x1
WST.0212	400x80x12mm	x1
WST.0081	418x80x12mm	x1


Colli
3/3











KUH.10242	580x290x16mm	x2
KUH.40120	995x276x16mm	x2
KUH.40122	995x276x16mm	x1
KUH.60175	1013x287x2,5mm	x1
KUH.60176	1013x287x2,5mm	x1
KUH.70588	1024x294x16mm	x1

$\varnothing 6 \times 30 \text{mm}$	$6,4 \times 50 \text{mm}$		$\varnothing 35/0 \text{mm}$	
12	12	12	2	2
	$\varnothing 3,0 \times 25 \text{mm}$			$\varnothing 3,5 \times 13 \text{mm}$
2	1	3	1	6
$\varnothing 3,0 \times 20 \text{mm}$	$\varnothing 4,0 \times 30 \text{mm}$	$\varnothing 4,0 \times 30 \text{mm}$	$L=128 \text{mm}$	
15-20	4	2	1	

1




$\pm 8 \times 30 \text{mm}$ A 12	 K 2	$\pm 4.0 \times 30 \text{mm}$ P8 4
$\pm 35/0 \text{mm}$ HG 2	$\pm 3.5 \times 13 \text{mm}$ P5 4	




2

6,4 x 50mm






B

6




O

1




3

6,4 x 50mm






B

6



O

1



4

+3.0x20mm










P7









15-20









L2

3









6



$\pm 3.0 \times 25 \text{ mm}$ K36 1
$\pm 3.5 \times 13 \text{ mm}$ P5 2



 E1 12	$L=128 \text{ mm}$ S 1	$\pm 4.0 \times 30 \text{ mm}$ R2 2
----------------------------	--	---