




06410015-03

1217501



festziehen ytighen уЗатенер у
serrer ystringere utáhnout yvastrekken y
zategnuti ystrangere yzwiazac y
szorosan meghúzni urevne dotiahnut' y
trdno pritegniti uzatyanyt' ydra at y



eindrücken ypress in yenfocer y
ribattere yzatlačit yВкарайте у
Benyomni ystlacit' yvtisniti utryck iny
introducere prin apasare удавить у



ausmessen ymeasure ymesures y
misurare yopmeten yizmeriti ymiara y
kiméni yizmeriti ymasurare uyizmerit' y
změřit' yИзмерете умат upp y









drücken ypress ypresser ystisknout y
HaTNCHeTe yvtisniti ynasinac ydrukken y
pritisnuti ynacisnac upritisniti унажать у
ИМегЗуомни уapasare utryck fast y





























einschlagen yhammer in ybeverni ysla in
frapper au marteler yinfossare yZabit' y
zarazit уЗабийте И чукЗузabiti y
Introducere prin bataie узабить у











Drehenowenden yProsze odwrócić y
Kerenomdraaien yGirareRuotare y
Okrenutiubrnuti yRetournerenverser y
Turn overduim around уOtoctecobratte y
Обърнетесавъртет уObrnite list y
Intoarceți yrotiti yVrid runt cvänd y








A  $\varnothing 15$ 52x	B  52x	C  $\varnothing 8 \times 30$ 40x	D  $\varnothing 3.5 \times 12$ 59x	E  14" 6x
F  $\varnothing 4 \times 30$ 12x	G  4x	H  $\varnothing 4 \times 14$ 24x	I  $\varnothing 3 \times 18$ 10x	K  80x15x10mm 5x
L  1x	M  $\varnothing 50 \times 3$ 4x	N  M6x15 22x	O  M6x25 4x	P  $\varnothing 20 \times 0.4$ 20x
Q  110x50x9 2x	R  $\varnothing 9 \times 2$ 2x	S  2x	T  $\varnothing 4 \times 50$ 2x	U  2x
V  1x	W  1x	X  1x	Y  $\varnothing 8 \times 12$ 18x	Z  2x







Step:1











Step:2





Step: 3






Step: 4





Step: 5

A	 ø15	P	 ø20x0.4
14x		2x	












Step: 6

Z	
2x	








Step: 7

L		M	 ø50x3	N	 M6x15	U		V	
	1x		4x		18x		2x		1x
Y	 ø8*12								
	18x								







Step: 8

B		C	 ø8x30
	6x		2x




Step: 9


A  $\varnothing 15$	P  $\varnothing 20 \times 0.4$
6x	6x



Step: 10








Step: 11









11


12





Step: 12








Step: 13






A	 ø15
8x	

L	
1x	







N	 M6x15
6x	









Step: 14






Step: 15




Step: 16




Step: 17





Step: 18




Step: 19







Step: 20




+





Step: 21





Step: 22





D

 ø3.5*12
8x





H

 ø4x14
8x

W

1x


X

1x





Step: 23



Step: 24

H

ø4x14
8x



Step: 25

