



D	Montageanleitung	GB	Assembly instructions
FR	Notice de montage	IT	Istruzioni di montaggio
NL	Handleiding voor de montage	PL	Instrukcja montażu
CZ	Montážní návod	SK	Návod na montáž
HU	Szerelési útmutató	RO	Instructiuni de montaj
TR	Montaj talimatı	RU	Инструкция по монтажу

4264.68 Ohio



Service • Assistenza • Dienstverlening • Serwis

Servis • Szerviz • Сервисная служба

Name • Nom • Nome • Naam




Nazwa • Jméno • Názov • Név

Denumire • İsim • Название

Nr. • No. • N° • Номер • Č • Sz

Typ • Type • Tip • Típus • Tipo


Тип



Ax12




Bx12





Cx1



Dx4



1 x1
2 x4

A

Achtung:
Bitte Schraube A vorsichtig von Hand eindrehen.
Bitte keinen Akkuschrauber benutzen.
Please screw in part A by hand.
Please do not us a cordless drill.

