















Modell: **EDGE**



Art. Nr. 14160023/04





1	1822	402	27	x1	2/4
2	1822	402	27	x1	2/4
3	764	401	27	x1	3/4
4	764	401	27	x1	3/4
5	732	357	16	x1	1/4
6	1178	357	16	x1	1/4
7	571	352	16	x1	1/4
8	1192	370	3	x1	4/4

9	746	586	3	x1	4/4
10	1192	374	3	x1	4/4
11	1192	373	20	x1	4/4
12	754	290	20	x2	4/4
13	754	295	20	x2	4/4
14	150	20	20	x2	1/4
15	370	150	20	x2	1/4
16	350	120	16	x2	1/4


17	350	120	16	x2	1/4
18	1120	120	16	x2	1/4
19	1130	344	3	x2	4/4
20	1194	185	20	x2	1/4
21	244	150	20	x2	1/4




EDGE Art. Nr. 14160023/04




A

f1  $\phi 8 \times 30$ mm x24	r16  x24	r1  x24	e1  $\phi 6.5 \times 50$ mm x8	s1  x8	s2  x24
s11  x1					


B





p4  $\phi 3.5 \times 16$ mm x15	p70  $\phi 4 \times 40$ mm x8	l9  x7	p1  $\phi 3.5 \times 13$ mm x70	d1  $\phi 5 \times 17$ mm x4	k2  x4
--	--	--	--	---	--













C

c8  x8	t15  x6	j35  $\phi 6 \times 30$ mm x4	z1  x1	o21  x12	l2  x35
--	---	--	--	---	---

D

t17  $\phi 8 \times 50$ mm x2	n14  x2
--	---





2

f1

φ8x30 mm

x12

r16

x4

r1

x12







b12





x3

e2


φ6.3x13 mm

x6








4








5








s2

x12





7	l9  x7	l2  x11	p4  $\phi 3.5 \times 16$ mm x15	p70  $\phi 4 \times 40$ mm x8	j35  $\phi 6 \times 30$ mm x4	k2  x4
----------	---	--	---	---	--	---



8

f1





φ8x30 mm

r1




x8




9

r16



x8




10


e1



z1



s1




φ6.5x50 mm

x8


x1


x8

e1



z1






s1



e1



16




e1

s1

e1

s1


17



e1

e1


18



x2

11

w350



L-350

x2


p1




φ3.5x13 mm

x12

!




16



w350

17



w350

x2

p1

p1

p1

p1

p1

p1

w350

p1

p1

11/19

12

s2



x8

l2



x24

t15










x6

p1



φ3.5x13 mm

x12



13


p1



φ3.5x13 mm


x6

a2



x3

m25










x2

o21



x2



14


p1



φ3.5x13 mm

x8

a12




x2

o21



x4

a2



x2

