

























HENRY



60 min


 M8x16	 M8x20	 3,5x30			 M8x60
A x 4	B x 24	C x 18	D x 6	E x 4	F x 4
		 L	 R		 M6x16
G x 4	H x 4	I x 1	J x 1	K x 2	L x 4
	 M8	 #13	 #5	 #4	 4x16
M x 2	N x 4	O x 1	P x 1	R x 1	S x 16
					
T x 2					

			
① x 1 (C1)	② x 1 (C1)	③ x 1 (C1)	④ x 1 (C1)
			
⑤ x 3 (C1)	⑥ x 1 (C2)	⑦ x 1 (C3)	⑧ x 4 (C3)




M8x20

B x 16




H x 4



#5


P x 1

1




screw all bolts 50%

2

XX = YY $\cong$ 90°

screw all bolts 100%




3,5x30
C x 12




D x 4




E x 4






3,5x30
C x 6



4x16
S x 16

5




M8x20
B x 8



L
I x 1

R
J x 1


#5
P x 1

6







Option A




Option B



9




10




D x 2


T x 2

11



12

