










A	B	C	D
1	S471-0001	803	496 2/2
2	S471-0002	1020	265 2/2
3	S471-0003	1020	265 2/2
4	S471-0004	1020	265 2/2
5	S471-1001	811	419 2/2
6	S471-1002	811	419 2/2
7	S471-1003	811	381 1/2
8	S471-2001	1560	422 1/2
9	S471-2002	1560	419 1/2
10	S471-3001	494	375 1/2
11	S471-4001	1480	60 1/2
12	S471-4002	329	60 1/2
13	S471-4007	1019	60 2/2
14	S471-9001	979	357 1/2
15	S471-9002	839	506 2/2
16	S471-9301	839	1031 2/2
17	ZK3-5119	969	127 1/2
18	ZK4-513	350	140 1/2
19	ZK4-514	350	140 1/2




1x a203	1x a210	2x b90	4x c485	4x d1	6x e1	34x f1	12x f25	6x f9
6x k1	10x l2	4x n108	8x p1	36x p140	6x p25	6x p35	19x p38	4x p51
4x p55	22x r1	12x r15	34x r42	6x t35	6x w210\1	6x w210\2	2x s68	1x z1
1x n26\1								


1





2





3



4



5



6









Diagram 13 illustrates the process of attaching the side panel (6) to the main panel (7). A long, thin metal bracket (13) is shown being aligned with the side panel. The bracket is secured to the side panel using two screws (r1). The main panel (7) is shown in the background, indicating its position relative to the side panel.



9



10

