


1/7



B1
φ 8x28 x16

T1
x16

M1
x16

C2
φ 20 x16

J23
x8

P2
3x16 x3

U20
x1

P4
4x25 x2

F37
x6

S9
4x16 x12

J11
x2

P13
3,5x13 x4

T17
φ8x50
5x60 x2


X15
x2

S8
4x13 x4

D2
x2




X19
x1

Nr	Ausmaß			St
1	366	417	15	1
2	366	417	15	1
3	360	360	15	1
4	366	364	15	1
5	804	362	15	1
6	1200	420	15	1
7	1200	420	32	1
8	1180	380	2	1





1

- (B1)**  $\varnothing$ 8x28 x8
- (T1)**  x2
- (D2)**  x2








2




- (B1)**  $\varnothing$ 8x28 x8
- (T1)**  x2






3





4




5



6  x4






7  x6



8



M1  x6



9

J23  x8

P2  3x16 x3



10

