








ASSEMBLY INSTRUCTION CORNER BENCH - AUFBAUANLEITUNG - INSTRUKCJA MONTAŻU - MONTÁŽNÍ NÁVOD

2257



LIST OF FURNITURE HARDWARE - BESCHLAGTEILE - OKUCIE ŁĄCZĄCEŁ - SPOJOVACÍ KOVÁNÍ

A  5x	B  2x	C  4x	D  4x	E  5x20 8x	F  7x50 3x
G  8x30 4x	H  M6x50 6x	I  M6x40 4x	J  M6x30 10x	K  M6x65 4x	L  M6x20 18x
M  4x16 20x	N  10x	O  10x	P  3x	Q  4x60 1x	R  1x




Here, you can measure the furniture hardware to recognise a certain part according to its size. All proportions are in millimetre.

Hier können Sie die Schrauben zur besseren Identifizierung nachmessen (alle Maßangaben in mm).


Tutaj mogą sobie Państwo zmierzyć okucie do dokładnego ustalenia rodzaju według rozmiarów. Wszystkie rozmiary podawane są w milimetrach.

Zde si můžete změřit kování k přesnému určení typu dle velikosti. Všechny rozměry jsou uvedeny v milimetrech.


45 min.




BENCH SECTIONS
BAUTEILE
CZĘŚCI
DÍLY




1




2




3



4



5



6

