








Assembly Instruction

KOMMODE MALIN

Article number: 05540001/05



286 X 1 PCS	249 X 7 PCS	5694 X 6 PCS	565 X 1 PCS	180964 X 1 PCS	122439 X 4 PCS	145662 X 16 PCS
95200 X 1 PCS	147 X 38 PCS	146 X 12 PCS	175 X 16 PCS	361 X 8 PCS	172 X 12 PCS	4997 X 16 PCS
81062 X 4 PCS	103 X 4 PCS	100 X 28 PCS	101 X 28 PCS	298176 X 8 PCS	150217 X 4 SET	150218 X 4 SET
298172 X 2 PCS	298171 X 1 PCS	298173 X 3 PCS	157124 X 28 PCS	22018 X 24 PCS	298177 X 5 PCS	298188 X 6 PCS

1

The diagram illustrates the assembly of a rectangular frame with legs and casters. It consists of two main views of the frame, labeled with a circled '2'.

Top View:

- Four legs (249) are attached to the corners of the frame using screws (298188 optional 305058).
- Four casters (100) are attached to the bottom edge of the frame using screws (172).
- Callouts show the use of a screwdriver (101) to install the casters.
- A callout shows a hand turning a piece (part) around.

Bottom View:

- Four legs (249) are attached to the corners of the frame using screws (298188 optional 305058).
- Four casters (100) are attached to the top edge of the frame using screws (172).
- Callouts show the use of a screwdriver (101) to install the casters.
- A callout shows a hand turning a piece (part) around.

Parts and Tools:

- 249: Legs
- 298188 optional 305058: Screws for legs
- 100: Casters
- 172: Screws for casters
- 101: Screwdriver

2

150217

175 x2

100

103

5


TURN AROUND THE PIECE (PART) !

298176


5

298176


3




4




7




8




9




10




11




12




13



14



15



16

