

0
10
20
30
40
50
60
70



Service • Assistenza • Dienstverlening • Serwis • Servis • Szerviz • Сервисная служба

Name • Nom • Nome • Naam •
Nazwa • Jméno • Názov • Név •
Denumire • Ísim • Название

PORTLAND



Nr. • No. • N° •
Номер • Č • Sz

POR17T10


Typ • Type • Tip •
Typus • Tipo • Тип

10

31



PR4



X...

G4



X...

M12



4x12 mm

X...

C3



X...

W1



X...

W2



X...

L4



X...

F58



X...


S20



4x20 mm

X...

J11



X...

P13



3,5x13 mm

X...


G22



φ18

X...

T17




X...

T1



X...

MW1



X...

B1



φ 8x28 mm


X...

T6



X...

MW2




X...

M1




X...

T32



X...

MW2



X...

S17



3,5x17 mm

X...

J23



X...


S35



3,5x35 mm

X...

MH2



X...

P35



4x35 mm

X...

P16



3,5x16 mm

X...

