























25100019-01




BDSK Handels GmbH & Co. KG
Mergentheimer Straße 59
DE-97084 Würzburg
Germany
MID.YOU










A x42  L35	B x42  m15x12	C x28  m6x30	D x6  m6x45	E x1  m4	F x8 	H x114  m3x16
H2 x18  m3x12	H3 x2  m3x18	G x8 	K x10 	L x4 	M x4  m4x20	N x2 
P x2  m4x38	Q x2  m6x40	V x1 	X x28 			




1




A x42
L35






2



C x28



3



F x8





H2 x16








H3 x2




N x2



4

H x46  m3x16	G x8 
K x10 	L x4 
M x4  m4x20	





5



B x15







m15x12



6



B	x6	H2	x2
			
m15x12		m3x12	

V	x1
	






7


B x21
m15x12





8



D	x6	E	x1
			
m6x45		m4	



H2	x2
	
m3x12	

V	x1
	






9





H	x28	X	x28
			
m3x16			



10

P	x2	Q	x2
			
m4x38		m6x40	



 I	 II
 III	 IV

11

H x30



m3x16

