











EASY TYP 105



EASY TYP 105

MM

260

250

240

230

220

210

200

190

180

170

160

150

140

130

120

110

100

90

80

70

60

50









40


30

20

10

0



A0 8 x 30mm 	B1 f 7 x 50 mm 	C0  x6
C2  x14	C7 16mm  x14	D0 3 x 15 mm  x28
D5 3,5 x 16 mm  x20	D10 4 x 16 mm  x8	D16 4,2 x 28 mm  x8
D21 5 x 13 mm  x13	E0 5 x 50 mm 8 x 50 mm  x1	J4  x4
J6  x4	K 4mm  x1	L5  x4
M1  x24	N1 L-300  x2	P0  x1
P20  x4	Q3  x12	T3  x6
U0  x6		




EASY TYP 105

1	812	350	16	x1	1/2
2	812	350	16	x1	1/2
3	750	332	16	x1	1/2
4	686	52	16	x1	2/2
5	300	90	16	x2	2/2
6	300	90	16	x2	2/2
7	278	87	16	x2	2/2
8	686	332	16	x1	2/2

9	335	310	16	x3	2/2
10	494	340	16	x1	1/2
11	754	340	16	x1	1/2
12	340	128	16	x2	1/2
13	720	360	22	x1	2/2
14	760	344	2,8	x1	1/2
15	760	344	2,8	x1	1/2
16	288	294	2,8	x2	1/2
					2/2




x2






1 ►

A0 8 x 30mm 	C2 	C7 16mm
D0 3 x 15 mm 	D21 5 x 13 mm 	J6
N1 L-300 	Q3 	T3





2 ▶

A0	8 x 30mm	x2	C2		x2	C7		x2
						16mm		
J6		x2	Q3		x4	T3		x2
								




3 ▶

A0 8 x 30mm x4 	C7 16mm x2 	D0 3 x 15 mm x2 
D21 5 x 13 mm x6 	N1 L-300 x2 	
Q3 x6 		




4

C2	x6	D21	5 x 13 mm	x1	P0	x1
-----------	-----------	------------	-----------	-----------	-----------	-----------




5

A0	8 x 30mm	x4	C7	16mm	x4
-----------	----------	-----------	-----------	------	-----------






6







A0	8 x 30mm	x2	D5	3,5 x 16 mm	x4	P20	x4
			T3	x2			




7





8








9 ►



10 ►




11▶











12▶


E0



x1





13 ▶




A0	8 x 30mm	x2
		
C7		x2
16mm		

14 ▶




A0	8 x 30mm	x2
		
C7		x2
16mm		


15 ▶




A0	8 x 30mm	x4
		

16 ▶





C2		x4
		
D16	4,2 x 28 mm	x4
		
L5		x2
		
U0		x2
		

17 ▶




B1	f 7x 50 mm	x4
		
K	4mm	x1
		




18▶




19▶




a=b




(D0)	3 x 15 mm	x8
		
(D5)	3,5 x 16 mm	x12
		
(M1)		x8
		
(N1)	L-300	x2
		




20 ▶



21 ▶



22▶



23▶

