











EASY TYP 201/202



EASY TYP 201/202

MM

260

250

240

230

220

210

200

190

180

170

160

150

140

130

120

110

100

90

80

70

60

50






40


30

20


10

0

A0 8 x 30mm 	C0 	C2 
C7 16mm 	D0 3 x 15 mm 	D5 3,5 x 16 mm 
D21 5 x 13 mm 	E0 5 x 50 mm 8 x 50 mm 	M1 
P0 	P20 	Q3 
T3 		




EASY TYP 201/202




TYP 201

1	812	350	16	x1	1/1
2	812	350	16	x1	1/1
3	516	52	16	x1	1/1
4	516	332	16	x1	1/1
5	516	310	16	x2	1/1
6	550	360	22	x1	1/1
7	760	526	2,8	x1	1/1
					1/1




TYP 202

1	812	350	16	x1	1/1
2	812	350	16	x1	1/1
3	686	52	16	x1	1/1
4	686	332	16	x1	1/1
5	686	310	16	x2	1/1
6	720	360	22	x1	1/1
7	760	696	2,8	x1	1/1
					1/1




1 ▶

A0 8 x 30mm 	x2	C2 	x2	C7 16mm 	x2
Q3 	x4	T3 	x2		





2 ▶

A0 8 x 30mm 	x2	C2 	x2	C7 16mm 	x2
		Q3 	x4	T3 	x2







3

(C2)  x4	(D21) 5 x 13 mm  x1	(P0)  x1
---	---	---




4

(A0) 8 x 30mm  x2	(D5) 3,5 x 16 mm  x4	(P20)  x4
(T3)  x2	 	






5




(A0) 8 x 30mm  x4	(C7) 16mm  x4
---	---




6





7



8 ►









9 ►












10▶

(D0)	3 x 15 mm 	x10
(M1)		x10



11 ▶



12▶

