






















ASSEMBLY INSTRUCTION - 29130019/01






ASSEMBLY INSTRUCTION - 29130019/01














A		x72
B	 M6x20 mm	x30
C	 M6x35 mm	x20

D	 M6x40 mm	x10
E	 M6x110mm	x2
F		x4






G	 160 N	x2
H	 100 N	x1
		x2

ASSEMBLY INSTRUCTION - 29130019/01




A		x72
B	 M6x20mm	x30
C	 M6x35mm	x20
D	 M6x40mm	x10
E	 M6x110mm	x2
F		x4
G	 160N	x2
H	 100N	x1
		x2

ASSEMBLY INSTRUCTION - 29130019/01








A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2






ASSEMBLY INSTRUCTION - 29130019/01



A		x72
B		x30
C		x20
D		x10
E		x2
F		x4
G		x2
H		x1
		x2








ASSEMBLY INSTRUCTION - 29130019/01




A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2

ASSEMBLY INSTRUCTION - 29130019/01




A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2



ASSEMBLY INSTRUCTION - 29130019/01




A		x72
B		x30
C		x20
D		x10
E		x2
F		x4
G		x2
H		x1
		x2








A



A




ASSEMBLY INSTRUCTION - 29130019/01




A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2



ASSEMBLY INSTRUCTION - 29130019/01



A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2




ASSEMBLY INSTRUCTION - 29130019/01







A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2






ASSEMBLY INSTRUCTION - 29130019/01



A		x72
B		x30
C		x20
D		x10
E		x2
F		x4
G		x2
H		x1
		x2








ASSEMBLY INSTRUCTION - 29130019/01










A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2

ASSEMBLY INSTRUCTION - 29130019/01








A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2










ASSEMBLY INSTRUCTION - 29130019/01



A		x72
B	M6x20mm	x30
C	M6x35mm	x20
D	M6x40mm	x10
E	M6x110mm	x2
F		x4
G	160N	x2
H	100N	x1
		x2

ASSEMBLY INSTRUCTION - 29130019/01



A		x72
B	 M6x20mm	x30
C	 M6x35mm	x20
D	 M6x40mm	x10
E	 M6x110mm	x2
F		x4
G	 160N	x2
H	 100N	x1
		x2

