
















KIMI




2/8

KIMI



nr	L[mm]	B[mm]	T[mm]	Menge	Coll.
1	1210	498	28	1	1/2
2	450	478	16	1	1/2
3	720	492	28	1	1/2
4	584	478	16	1	2/2
5	584	478	16	1	2/2
6	727	120	16	1	2/2
7	616	429	3	1	2/2
8	350	120	16	1	2/2
9	414	120	16	1	2/2
10	444	203	16	3	2/2
11	400	100	12	1	2/2
12	400	100	12	1	2/2
13	384	100	12	1	2/2
14	616	429	3	3	1/2





A3 $\varnothing 6 \times 42$ x...(12)	A1 $\varnothing 7 \times 50$ x...(4)	W2 x...(1)	F4 x...(2)	F12 x...(6)
H5 400mm x...(6)	I1 x...(6)	W1 x...(2)	G46 6x8 x...(12)	G34 3,5x16 x...(28)
K1 $\varnothing 15 \times 12$ x...(10)	G8 4x30 x...(6)	N1 M4x9 x...(6)	W3 x...(6)	E1 128mm x...(3)
K5 x...(10)	B1 $\varnothing 8 \times 35$ x...(10)	I7 x...(10)	P4 x...(8)	

3/8


KIMI




I













x3



0,5h



II




4/8




KIMI



III



IV






5/8


KIMI





V



VI



VII





6/8




KIMI



VIII



IX






7/8



KIMI



X

 $a=b$ 

XI



8/8

KIMI



XII

