












25100017-01








A x32  L35	B x32  m15x12	C x24  m6x30	D x6  m6x45	E x1 	F x2 	H x43  m3x16
H3 x2  m3x18	G x2 	K x3 	L x1 	M x1  m4x20	N x2 	P x2  m4x38
Q x2  m6x40	X x17 					









1







2

C x24 m6x30 	F x2 	H x4 m3x16 
H3 x2 m3x18 	N x2 	



3

H x13  m3x16	G x2 
K x3 	L x1 
M x1  m4x20	





4

B x12





m15x12



5



B x4
m15x12



6

B x16


m15x12




7



D x6
m6x45

E x1



8

H	x17	X	x17
			
m3x16			




9

H x9








m3x16



10

P	x2	Q	x2
			
m4x38		m6x40	



 I	 II
 III	 IV