









EASY TYP 109



EASY TYP 109

MM

260

250

240

230

220

210

200

190

180

170

160

150

140

130

120

110

100

90

80

70

60

50












40


30

20

10

0



A0 8 x 30mm 	x22	B0 	x3	B1 f 7 x 50 mm 	x9
C0 	x6	C2 	x14	C7 16mm 	x14
D0 3 x 15 mm 	x30	D5 3,5 x 16 mm 	x22	D10 4 x 16 mm 	x12
D16 4,2 x 28 mm 	x10	D21 5 x 13 mm 	x14	E0 5 x 50 mm 8 x 50 mm 	x2
J4 	x4	J5 	x2	J6 	x6
K 4mm 	x1	L5 	x5	M1 	x26
N1 L-300 	x2	P0 	x2	P20 	x5
Q3 	x20	Q4 	x2	T3 	x8
U0 	x6				




EASY TYP 109




1	1072	350	16	x1	2/2
2	1072	350	16	x1	2/2
3	1010	332	16	x1	2/2
4	1028	52	16	x1	2/2
5	300	90	16	x2	2/2
6	300	90	16	x2	2/2
7	278	87	16	x2	1/2
8	1028	332	16	x1	2/2
9	335	310	16	x2	2/2
10	677	310	16	x3	1/2


11	1014	340	16	x1	1/2
12	754	340	16	x1	1/2
13	1014	340	16	x1	1/2
14	340	128	16	x2	1/2
15	1028	46	22	x1	1/2
16	1062	360	22	x1	2/2
17	288	294	2,8	x2	2/2
18	1020	686	2,8	x1	1/2
19	1020	344	2,8	x1	1/2
					1/2








1

A0 8 x 30mm 	C2 	C7 16mm 
D0 3 x 15 mm 	D21 5 x 13 mm 	J6 
N1 L-300 	Q3 	T3 







2

A0 8 x 30mm 	x2	C2 	x2	C7 16mm 	x2
J6 	x2	Q3 	x6	T3 	x2




3



A0 8 x 30mm 	x4	C7 16mm 	x2	D0 3 x 15 mm 	x2
D21 5 x 13 mm 	x6	J6 	x2		
N1 L-300 	x2	Q3 	x10		



4 ▶


(C2)  x6	(D21) 5 x 13 mm  x2	(P0)  x2
---	---	---

(Q4)  x2






5 ▶



(A0) 8 x 30mm  x4	(C7) 16mm  x4
---	--




6 ▶

(A0) 8 x 30mm  x2	(D5) 3,5 x 16 mm  x5	(P20)  x5
---	--	--




(T3)  x2





7 ▶




8 ▶





9 ▶










10 ►












11 ►




12▶



13




14 ▶




A0	8 x 30mm	x2
C7		x2
16mm		

15 ▶




A0	8 x 30mm	x2
C7		x2
16mm		

16 ▶




A0	8 x 30mm	x4

17 ▶





C2		x4
D16	4,2 x 28 mm	x4
L5		x2
U0		x2

18 ▶




B1	f 7x 50 mm	x4
K	4mm	x1




19▶




20▶




a=b




(D0)	3 x 15 mm	x8
		
(D5)	3,5 x 16 mm	x12
		
(M1)		x8
		
(N1)	L-300	x2
		







21▶





22▶



23

D10 4 x 16 mm x4 	D16 4,2 x 28 mm x2 	J4  x2
		L5  x1
		U0  x2



24

