



ASSEMBLY INSTRUCTION- 23040033-02




ASSEMBLY INSTRUCTION- 23040033-02


A|2pcs




B|2pcs




C|2pcs




D|2pcs




A1|1pc




B1|1pc




C1|1pc




D1|1pc



E|1pc




F1|1pc




F2|1pc




F3|2pcs




F4|2pcs














F5|1pc



F6|1pc




ASSEMBLY INSTRUCTION- 23040033-02


G 1pc		G1 2pcs		H 1pc	
					
H1 2pcs		H2 2pcs		H3 3pcs	
					
H4 2pcs	I 2pcs	J 1pc		K 1pc	
					
① 19pcs		② 41pcs		③ 6pcs	
					
M6x30		M6x20		M6x15	
				④ 62pcs	
					
				M6	
				⑤ 10pcs	
					
				M6x2	
				⑥ 4pcs	
					
				M6x5	
⑦ 10pcs		⑧ 1pc		⑨ 1pc	
					
M6				M4	
				⑩ 2pcs	
					
				⑪ 2pcs	
					

ASSEMBLY INSTRUCTION- 23040033-02


1 x 2



2 x 2




3 x 2




ASSEMBLY INSTRUCTION- 23040033-02

4




5




ASSEMBLY INSTRUCTION- 23040033-02

6



②x5	④x5
M6x20	M6


7




②x4	④x4
M6x20	M6

ASSEMBLY INSTRUCTION- 23040033-02

8





9



ASSEMBLY INSTRUCTION- 23040033-02



10



①x10	④x10	⑤x10	⑦x10
			
M6x30	M6	M6x2	M6

ASSEMBLY INSTRUCTION- 23040033-02


11




②x4 ! M6x20	⑥x4 @ M6x5
-------------------	------------------

ASSEMBLY INSTRUCTION- 23040033-02

12




13




ASSEMBLY INSTRUCTION- 23040033-02

14



15



①x8 M6x30	③x4 M6x15	④x12 M6
--------------	--------------	------------

16

