



90 min


US 30

00020010-05



 A	 B	 B2	 C5	 D2					
12	8	2	2	2					
 E1	 E9	 F2	 HG	 L1	 J	 L	 M2	 O	 P4
8	2	4	2	1	4	2	8	1	2
 P5	 P7	 R3	 S	 T15	 T14	 U8			
8	6	4	2	2	2	4			

ISM-KUH-01235



KUH.60273



KUH.30038






KUH.40004

KUH.10343	815x550x16
KUH.10344	815x550x16
KUH.20062	300x600x38
KUH.30038	266x430x16
KUH.40004	267x485x16
KUH.60091	713x285x2,5
KUH.60273	237x448x2,5
KUH.70819	133x296x19
KUH.70824	576x296x19
KUH.90001	267x100x16
KUH.90002	267x100x16
KUH.90017	299x95x16
WST.0115	450x80x12
WST.0116	450x80x12
WST.0146	227x80x12







1

$\pm 12/10\text{mm}$  C5 2	$\pm 8 \times 30\text{mm}$  A 4
--	---









2

$\pm 6 \times 42\text{mm}$  B2 2












3





$L=20\text{mm}$  D2 2
--










4






5







6.5x48x16 F2 4	8x30mm A 8	L=450mm L R 1	6.3x13mm M2 8	3.5x13mm P5 2	T15 2
----------------------	------------------	---------------------	---------------------	---------------------	----------









7

6,4 x 50mm		
		
B	O	E1
4	1	4







8




6,4 x 50mm		
		
B	O	E1
4	1	4


9




10





4




11



$\pm 4.0 \times 45 \text{mm}$  P4 2	 E9 2	$\pm 4.0 \times 35 \text{mm}$  R3 4	$\pm 3.5 \times 13 \text{mm}$  P5 2
---	--	---	---



2.






3.




12

$\pm 5/19 \text{mm}$  J 4
--







1.



2.



3.






8x20x100mm





T14

2






15














 HG 2	 P5 4
---	---





16



M4x27mm	
	
U8	S
4	2





4.0x27mm

