




2,5h








CALITAN Furniture Factory Sp. z o.o.

ul. Rakowska 1

63-645 Łęka Opatowska





E-Mail: export@calitanff.pl












nr	L[mm]	B[mm]	T[mm]	Menge	Colli
1	1900	396	16	1	1/7
2	1900	396	16	1	1/7
3	396	396	16	1	2/7
4	396	396	16	1	2/7
5	245	376	16	1	2/7
6	1867	376	16	1	2/7



nr	L[mm]	B[mm]	T[mm]	Menge	Colli
7	1867	135	16	1	1/7
8	296	135	16	1	2/7
9	1902	80	16	1	1/7
10	1898	120	16	1	1/7
11	354	120	16	3	2/7
12	1879	266	3	1	1/7

nr	L[mm]	B[mm]	T[mm]	Menge	Colli
13	945	285	16	2	2/7
14	300	140	12	2	2/7
15	300	140	12	2	2/7
16	877	126	16	2	2/7
17	887	306	3	2	1/7



Colli 7/7

G28  4x60 x2	U6  ø8x50 x2	G52  6x20 x4		
A6  ø7x40 x8	K4  ø12x10 x4	M11  x2	G50  6x13 x4	
F15  x6	F12  x6	H15  300mm x2	I29  8mm x4	
K1  ø15x12 x22	I7  ø18 x22	W2  x1	A1  ø7x50 x14	P4  x10
K10  x26	B1  ø8x35 x22	M13  300mm x2	I1  x10	G34  3,5x16 x74




K1

Ø15x12



x12

K10








x4


B1



Ø8x35


x12





II

K10



x14

K1



Ø15x12

x4

F12



x6

B1



Ø8x35










x4


G34




3,5x16

x6






III



W2



x1


A1




Ø7x50

x8


IV




K1





K10








V












VI





VII

 $A=B$ 





VIII

G34






3,5x16

x18





1.

2.






IX




F15		G34	
	x3	3,5x16	x12

X






XI




W2




x1

A1





ø7x50


x6





XII




XIII



F15		G34	
	x3	3,5x16	x12




XIV



P4	
x10	

XV

H15



300mm



x1

G50






6x13

x4





XVI

G52		6x20	x4	I29		8mm	x4
H15		300mm					x1












XVII

I7		
ø18		x22






XVIII



M13  300mm x2	W2  x1	A6  ø7x40 x8	K4  ø12x10 x4
		I1  x10	G34  3,5x16 x20
			K10  x4











XIX



XX

G28  4x60 x2	U6  ø8x50 x2	M11  x2	G34  3,5x16 x4
---	---	---	---










nr	L[mm]	B[mm]	T[mm]	Menge	Colli
18	1938	328	16	1	3/7
20	414	328	16	1	3/7
21	381	278	16	2	3/7
22	381	278	16	2	3/7








nr	L[mm]	B[mm]	T[mm]	Menge	Colli
23	1950	393	3	2	3/7
24	372	120	16	1	3/7
25	286	120	16	2	3/7
26	1964	408	34	1	5/7

nr	L[mm]	B[mm]	T[mm]	Menge	Colli
38	1938	328	16	1	3/7
39	414	328	16	1	3/7




Colli 7/7




	A1  $\varnothing 7 \times 50$ x6	W3  x3	I30  $\varnothing 14$ x42	F2  x8
F15  x2	G28  4×60 x1	U6  $\varnothing 8 \times 40$ x1	C3+D3  Z35PR x4	N7  $M4 \times 15$ x2
K1  $\varnothing 15 \times 12$ x16	I7  $\varnothing 18$ x16	W2  x1	P4  x6	
K10  x16	B1  $\varnothing 8 \times 35$ x16	M11  x1	I1  x12	G34  $3,5 \times 16$ x26

I




K1



B1

K10



x8

B1



ø8x35

x8


K1



ø15x12

x8


K10



39

K1


x2




21


B1

K10







20








II




A1		
ø7x50		x6
W2		
		x1



III









F15		
		x2
G34		
3,5x16		x8




IV


K10  x8	B1  ø8x35 x8	K1  ø15x12 x8	D3  x4
--	--	---	---




V




VI




VII



VIII













IX



A=B

G34 3,5x16 x8	I1 x12
---	--










nr	L[mm]	B[mm]	T[mm]	Menge	Colli
18	1938	328	16	1	4/7
20	414	308	16	1	4/7
21	381	278	16	2	4/7
22	381	278	16	2	4/7










nr	L[mm]	B[mm]	T[mm]	Menge	Colli
23	1950	393	3	2	4/7
24	372	120	16	1	4/7
25	286	120	16	2	4/7
26	1964	408	34	1	5/7

nr	L[mm]	B[mm]	T[mm]	Menge	Colli
38	1938	328	16	1	4/7
39	414	308	16	1	4/7



Colli 7/7







A1  ø7x50 x6	W3  x3	I18  x1	I30  ø14 x42	F2  x8
F15  x2	G28  4x60 x1	U6  ø8x40 x1	C3+D3  x4	N7  M4x15 x2
K1  ø15x12 x16	I7  ø18 x16	W2  x1	Z35PR  x4	P4  x6
K10  x16	B1  ø8x35 x16	M11  x1	I1  x12	G34  3,5x16 x26

I


K10 x8	B1 ø8x35 x8
	K1 ø15x12 x8


II




A1		
ø7x50		x6
W2		
		x1



III









F15		
		x2
G34		
3,5x16		x8




IV


K10  x8	B1  ø8x35 x8	K1  ø15x12 x8	D3  x4
--	---	--	---




V




VI



VII




VIII




P4  x6






P4

IX





A=B

G34	
3,5x16	x8
I1	
	x12







X






N7			W3	
M4x15		x4		x6





XI




F2  x16	M11  x2	G34  3,5x16 x4
I18  x1	G28  4x60 x2	U6  ø8x40 x2




- 1

- 2


XII





XIII









G34
3,5x16 x16

C3+D3
Z35PR x8











XIV




I7	I30
	
ø18	x32 ø14
	x12






nr	L[mm]	B[mm]	T[mm]	Menge	Colli
29	1900	328	16	2	6/7
30	268	328	16	2	6/7
31	268	308	16	1	6/7
32	945	305	16	2	6/7
33	1879	280	3	1	6/7








Colli 7/7


G28 4x60 x2	U6 ø8x40 x2	I7 ø18 x12	W3 x10	N7 M4x15 x4
K1 ø15x12 x12	I1 x10	C3+D3 x4	G32 3,5x16 x10	L7 80N x2
K10 x12	B1 ø8x35 x12	Z35PR x4	G34 3,5x16 x14	I4 ø5 x8

I


K1		K10		B1	
Ø15x12	x12		x12	Ø8x35	x12




II





III











IV



V





C3+D3	
	
Z35PR	x4
G34	
	
3,5x16	x8
G32	
	
3,5x16	x4








VI


A=B




I1  x10	G34  3,5x16 x3
--	---




VII




- G32
3,5x16x6
- L7
x2




VIII





- D3
x4




IX

G34 
3,5x16 x4
U20 
x2






X




N7	
M4x15	x4
W3	
	x4




XI


U6







ø8x40

x2












XII





G28
4x60 x2









XIII



14
ø5 x8



XIV





Uwaga • Upozornění • Achtung • Attention • Caution • Figyelem
Attenzione • Opgelet • Внимание • Atenție • Upozornenie • Dikkat

