






















|    |     |    |      | PCS |     |
|----|-----|----|------|-----|-----|
| 1  | 98  | 50 | 80   | × 1 | 1/4 |
| 1A | 98  | 72 | 20   | × 1 | 1/4 |
| 2  | 98  | 50 | 80   | × 1 | 2/4 |
| 2A | 98  | 72 | 20   | × 1 | 2/4 |
| 3  | 16  | 61 | 106  | × 1 | 3/4 |
| 4  | 16  | 61 | 106  | × 1 | 3/4 |
| 5  | 220 | 16 | 4    | × 1 | 4/4 |
| 6  | 100 | 50 | 13   | × 1 | 1/4 |
| 6  | 100 | 50 | 13   | × 1 | 2/4 |
| 7  | 21  | 26 | 20.7 | × 1 | 1/4 |





Stoffprobe im Reparaturfall  
Fabric sample in case of repair

