






















A	B	C1	C2	C3	D
1	S528-1007	652	205	16	1/1
2	S528-1008	652	205	16	1/1
3	S528-2005	381	235	28	1/1
4	S528-2006	381	228	16	1/1
5	S528-0003	646	376	19	1/1
6	S528-3004	348	175	16	1/1
7	S528-9005	662	358	2.5	1/1








2






3




4






A=B




5



6x




2x




4x

6


 $\phi 10 \text{ mm}$


f35



f35

p127



f35

p127



2x





2x


 $\phi 6 \times 60 \text{ mm}$
 $\phi 10 \times 50 \text{ mm}$

p127

f35

p127



p127

