







SPARKS 30J6_01

























NO	Dim.[mm]			Col.-No	Qty
1	1970	354	16	2/3	1
2	1970	354	16	2/3	1
3	568	374	16	1/3	1
4	568	354	16	1/3	1
5	534	334	16	1/3	1
6	1980	296	16	2/3	1
7	1980	186	16	3/3	1
8	1980	80	16	3/3	1
9	534	120	16	1/3	1
10	534	324	16	1/3	4
11	1982	273	3	2/3	2










120 min














SPARKS 30J6__01

A1 x16  ø8x36	A3 x8  Ø8x47	B4 x14 	B5 x30  ø15x12	B6 x8  Ø7x76	G5 x30 
E8 x4  H=0	E7 x4  Ø35 H=0	S1 x18 	ST7 x4 	G7 x16 	U18 x1  L-116mm.
C6 x1  L-300mm.	Z2 x8  Ø5	D10 X10  USØ3,5x13	UP6 x2  UPØ4x30	UP11 x4  UPØ4x20	UP9 X8  UPØ3,5x16
L1 x1 	KR1 x1 	G2 x1 			







1

B4		G7		A1		B5	
x3		x8		x4	$\varnothing 8 \times 36$	x4	$\varnothing 15 \times 12$







2

B4		G7		A1		B5	
x3		x8		x4	$\varnothing 8 \times 36$	x4	$\varnothing 15 \times 12$




3

B4		UP11		ST7	
x8		x4	UPØ4x20	x4	





4




A1		B5	
x8	ø8x36	x6	ø15x12




5




A3		B5	
x8	Ø8x47	x16	ø15x12




6





7



8




9






10




11






12



13



$X=Y$ 90°

UP9





x4




UPØ3,5x16

S1


x18











14 - 17





18 - 21








14








15

D10		L1		KR1	
x2	USØ3,5x13	x1		x1	




16



UP6


x2




UP04x30



U18





x1





L-116mm.









UP9		Z2		C6		E8	
x4	UPØ3,5x16	x8	Ø5	x1	L-300mm.	x4	H=0









19

D10		L1		KR1	
x2	USØ3,5x13	x1		x1	



20



UP6	 UPØ4x30	U18	 L-116mm.
x2		x1	

