



ASSEMBLY INSTRUCTION



23030006-01









A1		$\frac{104}{40.9}$	1 PC
A2		$\frac{94.5}{37.2}$	4 PCS
A3		$\frac{104}{40.9}$	1 PC
B1		$\frac{98}{35.8}$	1 PC
B3		$\frac{98}{35.8}$	1 PC

E		1 PC
F		1 PC

C1		$\frac{94}{37}$	1 PC
C3		$\frac{94}{37}$	1 PC
D1		$\frac{91}{35.8}$	1 PC
D3		$\frac{91}{35.8}$	1 PC

V		1 PC
W		1 PC

G		1 PC
H		1 PC
I		1 PC
J		1 PC
K		1 PC
L		1 PC
M		1 PC


N		1 PC
O		1 PC
P		1 PC
Q		1 PC
R		2 PCS
S		2 PCS
U		1 PC
Y		5 PCS
X		2 PCS

1	 M6 X20 mm	30 PCS
2	 M6 X30 mm	19 PCS
3	 M6 X40 mm	6 PCS


6	 M6 X40 $\phi 6 \times \frac{14 \times 1}{0.55 \times 0.04}$	80 PCS
7	 M6	8 PCS
9	 2 $\phi 6$	2 PCS
10	 4x60	

11		11 PCS
12	 M6 X $\frac{60}{2.7}$	6 PCS
13	 $\phi 6 \times \frac{14 \times 15}{0.55 \times 0.4}$	12 PCS
14		2 PCS
15		1 PCS



1




2




3








5




6






7




8





9






12



13





17

