


Assembly Instructions



HARDWARE LIST

- 1

x1
- 2

x2
- 3

x1
- 4

x1
- 5

x1
- 6

x1
- 7

x1
- 8


x1
- 9




x1
- 10

x2
- 11


x6
- 12

x1



					
A = 14+1	B = 14+1	C = 116+4	D = 2	E = 12	F = 22+1
					
G = 6	H = 4	I = 4	J = 4	K = 1	L = 6

STEP 1



Note: Please make sure the screws are not too loose or too tight, or skewed.



A x4pcs




B x4pcs




F x4pcs




STEP 2




Note: Please make sure the screws are not too loose or too tight, or skewed.

- A** x4pcs 
- B** x4pcs 
- F** x4pcs 



STEP 3





Note: Please make sure the screws are not too loose or too tight, or skewed.


A x6pcs 

B x6pcs 

C x36pcs 

E x6pcs 

F x6pcs 






STEP 4

C x36 pcs

E x6 pcs

L x6 pcs






STEP 5

G x6pcs



F x6 pcs



STEP 6


C x20 pcs



J x4 pcs





K x1 pc



STEP 7

J x4pcs




STEP 8

C x24 pcs

H x4 pcs

D x2 pcs



STEP 9

