






PEMBORKE



1/16

1815/PEMBORKE/161122/



2/16

3/16



1815/PEMBORKE/161122/

1815/PEMBORKE/161122/

A1  x 28	A2  x 28	B  x 12
C  M3.5 x 16 x 42	D  x 4	E  M3.5 x 12 x 16
F  x 4	G  x 1	H  x 5
I  x 1	J  x 4	K  x 6
L1  x 2	L2  x 2	M  x 4




4/16

1815/PEMBORKE/161122/




5/16

1815/PEMBORKE/161122/







6/16

1815/PEMBORKE/161122/



7/16

1815/PEMBORKE/161122/







8/16

1815/PENBORKE/161122/

9/16

1815/PENBORKE/161122/



10/16

1815/PENBORKE/161122/


11/16

1815/PENBORKE/161122/

15 x 2

13

x 1



17 x 2

E


M3.5
x 12

x 4

J2




x 2



16

A2

x 12



12/16

1815/PMBORKE/161122/

18

C


M3.5
x 16

x 6

K



x 6



13/16

1815/PMBORKE/161122/

19

12

x 1

L1

x 2


L2

x 2


C

M3.5
x 16


x 16



21




20



14/16

1815/PMBORKE/161122/

22



15/16

1815/PMBORKE/161122/

23

