





HOLDERVILLE












1/13

2388/HOLDERVILLE/250225/











2/13









2388/HOLDERVILLE/250225/

 x 1	 x 1	 x 1	 x 1	 x 1
 x 1	 x 1	 x 2	 x 1	 x 1
 x 1	 x 1	 x 1	 x 1	 x 1
 x 1	 x 24	 x 24	 x 14	 x 4
 x 4	 x 8	 x 1	 x 1	

3/13

2388/HOLDERVILLE/250225/





8/13

2388/MOLDVILLE/250225/

9/13




2388/MOLDVILLE/250225/

10/13

2388/MOLDVILLE/250225/


11/13

2388/MOLDVILLE/250225/



12/13

2388/MOLDVILLE/250225/



13/13

2388/MOLDVILLE/250225/