




ASSEMBLY INSTRUCTIONS




40'





2

1




2

A	x 73	B	x 73	C	x 38
					
Ø 6 x 35mm		Ø 15 x 12mm		Ø 8 x 30mm	
D	x 8	E	x 8	F	x 2
					
Ø 7 x 40mm		M3. 5 x 14mm			
G	x 6	H	x 12	I	x 6
					
		M6 x 12mm		M4 x 35mm	
J	x 1	K	x 1	L	x 1
					
M4 x 18mm				M4	
M	x 16				
					


3

1



A	x 16
	
Ø6x35mm	


2



A	x 8
	
Ø6x35mm	


4

3



B	x 4	C	4
			
Ø15x12mm		Ø8x30mm	


4



B	x 4	C	4
			
Ø15x12mm		Ø8x30mm	


5

5



B	x 4	C	2
			
Ø15x12mm		Ø8x30mm	


6



H	x 4	G	x 2
			
M6 x 12mm			


6

7



B	x 4	C	2
			
Ø15x12mm		Ø8x30mm	


8




H	x 4	G	x 2
			
M6 x 12mm			

7

9




10




8

11




12




9

13




14




10

15




16




11

17



B	x 4
	
ø15x12mm	


18	
----	--



A	x 27
	
ø6x35mm	


12

19



D	x 6	D	x 8
			
φ8 x 30mm		φ7 x 40mm	


20



C	10
	
$\varnothing 8 \times 30 \text{ mm}$	


13

21



B	x 27
	
$\phi 15 \times 12 \text{ mm}$	


22



A	x 6
	
ø6x35mm	


14

23




1	x 6
	
M4 x 35mm	

24




15

25



B	x 6
ø 15 x 12mm	


26




F	x 2	E	x 4	J	x 1	K	x 1
		M3.5 x 14mm		M4 x 18mm			

16

27



28



M	x 12

17