



ASSEMBLY DIAGRAM




Parts List

1: 1PC	2: 1PC	3: 2PCS	4: 1SET
5: 39PCS	6: 2PCS	7: 2PCS	8: 2PCS
9: 2PCS	10: 2PCS	11: 1PC	12: 2PCS
13: 1PC	14: 2PCS	15: 10PCS	16: 26PCS
17: 26PCS	18: 4PCS		


Hardware List

A: 18PCS	B: 8PCS	C: 22PCS	D: 8PCS	E: 4PCS	F: 18PCS
G: 26PCS	H: 26PCS	I: 34PCS	J: 1PC	K: 1PC	L: 1PC
M: 6PCS	N: 1PC				

STEP 1




	B x 8PCS
	H x 8PCS
	G x 8PCS
	J x 1PC
	18 x 4PCS



STEP 3



	E x 4PCS
	I x 4PCS
	K x 1PC
	9 x 2PCS




STEP 4

	C x 10PCS
	I x 10PCS
	15 x 10PCS

	C x 12PCS
	I x 12PCS
	K x 1PC
	6 x 2PCS




STEP 5




	D x 8PCS
	I x 8PCS
	K x 1PC

STEP 6




Note: Ensure that Frame assembly is square.

	A x 14PCS
	H x 14PCS
	G x 14PCS
	F x 14PCS
	J x 1PC
	L x 1PC
	10 x 2PCS
	11 x 1PC




STEP 7



	A x 4PCS
	H x 4PCS
	G x 4PCS
	F x 4PCS
	J x 1PC
	L x 1PC



STEP 8



	16 x 26PCS
	17 x 26PCS
	5 x 39PCS

STEP 9

Assembly Instructions
Please ensure the pneumatic arm is the correct orientation. The thinner section should be attached to the side rail, and the thicker part is connected to the slat frame. secure the pneumatic lifting mechanisms on the side rails place by using flange nuts as shown. Do not overtighten the nuts.





	N x 1PC
--	---------

STEP 10

Assembly Instructions

Please note: Before lowering the slat frame into position, place the mattress on the slat frame. The weight of the mattress will help with the lowering of the frame. Mattress weight limit: 50kgs. Assembly is completed.



	M x 6PCS
--	----------