



Assemble Instruction




HardwareList

A		M6*90	20	F		2
B		M10*15	20	G		8
C		M8*30	20	H		32
D		M6*40	4			1
E		M8*18	4			

Parts List




Step 1




A		M6*90	12
B		M10*15	12
C		M8*30	12

Step 2




C		M8*30	4	F		2
E		M8*18	4	G		8
D		M6*40	4			

Step 3



A		M6*90	8
B		M10*15	8
C		M8*30	4

Step 4



H		M4*30	32
---	---	-------	----