


















EASY TYP 308




EASY TYP 308



A0 8 x 30mm 	B1 7 x 50 mm 	C0 
C2 	C7 16mm 	D0 3 x 15 mm 
D10 4 x 16 mm 	D16 4,2 x 28 mm 	E0 5 x 50 mm 8 x 50 mm 
J4 	J5 	J6 
K 4mm 	L5 	M1 
Q4 	U0 	




EASY TYP 308




TYP 308

1	408	528	16	x1	1/1
2	408	528	16	x1	1/1
3	391,5	490	16	x1	1/1
4	402	511	16	x2	1/1
5	402	511	16	x1	1/1
6	1541	510	16	x1	1/1
7	1575	538	22	x1	1/1
8	401,5	1551	2,8	x1	1/1
					1/1




1 ►

A0 8 x 30mm 	C2 	C7 16mm 
J6 	x2	






2 ►

A0 8 x 30mm 	C2 	C7 16mm 
J6 	x2	






3

A0 8 x 30mm 	C7 16mm 	J6 	x4	x2	x2
--	--	--	-----------	-----------	-----------






4

D10 4 x 16 mm x8 	D16 4,2 x 28 mm x4 	J4 x4 
D10 		L5 x2 




5

D10 4 x 16 mm x4 	D16 4,2 x 28 mm x2 	J5  x2
		L5  x1






6

A0 8 x 30mm x4 	C7 16mm  x4
---	--




7



C2  x6	Q4  x2
--	--




8 ►




9 ►








10 ►












11 ►




12







13








14 ▶



15 ▶



16



17▶

