






Tina 1




1

2

3




R




L

1	1 x
2	1 x
3	1 x



1/1

A	M6X45	B	M6x13	C	Ø14xØ6x1.5	D	4MM	E	T2.0x90x90
									
4x		4x		4x		1x		1x	

I.

1

A	M6x45
	2x
C	Ø14xØ6x1.5
	2x
D	4MM
	1x
75%	

2

A	M6x45
	2x
C	Ø14xØ6x1.5
	2x
D	4MM
	1x
75%	

3

B	M6x13
	4x
D	4MM
	1x
E	T2.0x90x90
	1x
75%	

4

D	4MM
	1x
100%	