









ZOYA





Teil	Pcs	Colli	Teil	Pcs	Colli
1	1x	1/6	4	1x	4/6
2.1	1x	2/6	5	1x	5/6
2.2	1x	2/6	6	2x	6/6
3	1x	3/6	7	1x	1/6






A	B	C	D	E	F	G	H
4x	18x	2x	5x	1x	38x	2x	2x
H-150	3,5x35	H-150	ø 30		4x16	3,5x70	H-165
I	J	K	L	M	N		
4x	4x	14x	14x	1x	1x		
				H-68	H-150		





C	D
	
2x	2x
H-150	ø 30

1






2




A	B	D	E	F	N
					
4x	14x	1x	1x	10x	1x
H-150	3,5x35	ø 30		4x16	H-150

3




B	D	H	I	J	6
					
4x	2x	2x	4x	4x	2x
3,5x35	ø 30	H-165			


4




5




6





7





8





F		K		L	
	28x		14x		14x
4x16					

9




G  2x	M  1x
3,5x70	H-68



10




11



12



5  4x
M8