


















NIKA Sideboard



C2  x18	C6  x4	Q3  x8
C0  x4	U0  x6	D0 3 x 15 mm  x38
D10 4 x 16 mm  x8	D12 3.5 x 25 mm  x24	D16 4 x 30 mm  x8
D21 5 x 13 mm  x2	D24 5 x 22 mm  x17	B3 Ø8mm  x1
D31 6.3 x 13 mm  x16	E0 5 x 50 mm 8 x 50 mm  x2	P0  x2
K 4mm  x1	B1 f 7 x 50 mm  x22	M1  x36
J1  x4	J3  x4	N13 L-300  x2
T5  x6	L29  x4	


Option






G15  x1	G16  x1
--	--




1	1109	358	16	1	2/3
2	1109	358	16	1	2/3
3	1109	358	16	1	2/3
4	850	378	16	1	3/3
5	850	378	16	1	3/3
6	538	558	16	1	1/3
7	538	558	16	1	1/3
8	525	357	16	1	2/3
9	546	336	16	2	2/3
10	277	338	16	1	2/3
11	737	106	16	2	3/3
12	300	100	16	2	3/3
13	300	100	16	2	3/3
14	284	100	16	2	2/3


15	790	150	16	2	3/3
16	315	338	16	2	2/3
17	244	338	16	2	3/3
18	1143	380	10	1	3/3
19	1143	380	10	1	3/3
20	1119	286	3	1	3/3
21	555	534	3	2	1/3
22	747	294	3	2	3/3
23	326	302	16	1	3/3
					






3

(D31) 6.3 x 13 mm 	x8	(N13) L-300 	x2
--	-----------	--	-----------




4

(C2) 	x6	(D16) 4 x 30 mm 	x4	(L29) 	x2
(U0) 	x4				






5

(C6) 	x4
--	-----------





6

D10 4 x 16 mm 	J1 	D16 4 x 30 mm 
L29 	U0 	





7



D10 4 x 16 mm 	J1 	D16 4 x 30 mm 
L29 	U0 	





8





9




10







11





12






13



14









15




16

D0	3 x 15 mm	x28	M1		x28
					





17

D24	5 x 22 mm	x8
		







18

(D21)	5 x 13 mm 	x2	(P0)		x2	(Q3)		x8
--------------	--	-----------	-------------	--	-----------	-------------	--	-----------





19



(E0)	5 x 50 mm 8 x 50 mm 	x2
-------------	---	-----------




20



21







22



23



(D0) 3 x 15 mm 	x8	(M1) 	x8
---	-----------	--	-----------

a=b








24




(D24) 5 x 22 mm 	x1
--	-----------



25



26



27 Option →

